



Moment

Seating Upholstery Collection


GRADE 1




Azure
15041




Carbon
15020




Denim
15040



Merlot
15030




Paprika
15060




Pebble
15050



Pistachio
15011



Rouge
15031



Surf
15070



Taupe
15010

Moment

Grade	1
Content	57% Post-Consumer Recycled Polyester 19% Pre-Consumer Recycled Polyester 12% Pre-Consumer Recycled Nylon 12% Nylon
Finish/Backing	Stain Repellant/Acrylic
Antimicrobial	No
Flame Retardants	No
Repeat - Horizontal/Vertical	31.2" V/14"H
Railroad	No
Width	54"
Abrasion/Wyzenbeek (ASTM D4157)	100,000 Double rubs
Breaking Strength (ASTM D5034)	180 lbs. Warp, 120 lbs. Fill
Colorfastness to Light (AATCC 16.3)	Class 4/40 hrs
Crocking (AATCC 8)	Class 3 Wet, Class 4 Dry
Pilling (ASTM D3511)	Class 4
Seam Slippage (ASTM D4034)	55 lbs. Warp, 40 lbs. Fill
California TB 117-2013	Pass
Cleaning Code	WS
Bleach Disinfectable	10% bleach/water solution
Dye Transfer/Reverse Crocking	Some upholsteries may experience dye transfer (clothing dyes transfer to the seating fabric). This does not mean that the fabric of application is deficient, but rather it is an inherent characteristic of that fabric or application and is considered normal behavior. Once the dye transfer occurs, it is irreversible.

WS - Use water-based cleaning agents or foam. Mild water-free solvests may also be used. Cleaning by a professional furniture service is recommended.